



OBSERVATION WELLS ELIMINATED FROM RELIABILITY ANALYSIS, 1999



- Geologic boundary
 - - - Major aquifer limit
- Reasons for elimination:
- + Mechanical
 - x Erratic or abnormal behavior

PLATE 1
 Kansas Geological Survey
 OFR 99-15
 Olea & Davis